

Installing Your Linxup 1200 Wired Device

Prepare for the Installation.

To prepare for the installation you will need to:

 Review product and parts: Your shipping package should include the Linxup 1200
Wired GPS Tracker.

 Gather needed tools/parts. Needed tools may include: Screwdrivers, Wire Strippers and Cutters, Crimping Tool, Zip Ties, and Screws.



Install the Device.

Wiring the device is an easy installation. The Linxup


1200 has a series of wires, you will only need to attach two of

these wires (the additional wires are for future features or functions). The two wires you need are: the Red Wire (Power), and the Black Wire (Ground). Follow these steps to install the device:

- 1. Find the constant Red Power Wire on your asset. Cut and strip this wire.
- 2. Cut and strip the Red Wire on the Linxup 1200 GPS device.
- 3. Connect the two Red Wires and crimp. This connection provides power to the device.
- 4. Strip the Black Wire on the Linxup 1200 GPS device.
- 5. Connect the Linxup Black Wire to a grounded source.
- Using screws or plastic zip ties as appropriate, secure the device to your asset.

Confirm the Power Connection.

Following installation, allow 5-10 minutes for the Linxup device to power up, then use the LED indicators to ensure that you have good power source.



Your Installation is Complete.

PLEASE NOTE:

Your device monthly service plan is active upon delivery of the devices, not installation.